From: Gene Mitchell
To: Smith Maja
Subject: Oil change

Date: Friday, July 26, 2019 1:19:56 PM

I can't remember if I told you guys that the day before the accident I changed the oil and replaced the oil filter. In this process, I removed the cowling. What is interesting is that there was no indication on the bottom cowling of an oil leak. It was clean. After the oil change I started the engine and ran it up to average temps (oil pressure was 75 PSI) and then shut it down. I inspected for leaks and didn't find any. The new oil filter was safety wired. I then replaced the cowling.

Anyway, more information to dwell on.

Thanks

Gene Mitchell

Sent from Mail for Windows 10